

13



basic
laboratory

www.basiclab.com

voice 530.243.7234

fax 530.243.7494

2218 Railroad Avenue

Redding, California 96001

Report To:

[REDACTED]

BELLA VISTA, CA 96008

Attention:

[REDACTED]

Project:

GENERAL TESTING

Description:

EAST SIDE LAKE SHASTA

Matrix:

Water

Rain

Lab ID: 8051014-01

Lab No: 8051014

Reported: 06/11/08

Phone: [REDACTED]

P.O. #

Sampled: 05/25/08 08:00

Received: 05/30/08 09:40

Metals - Total

Analyte	Units	Results	Qualifier	MDL	RL	Method	Analyzed	Prepared	Batch
Aluminum	ug/l	525		30	100	EPA 6010B	06/05/08	06/02/08	88F0012

Notes and Definitions

J Detected but below the Reporting Limit; therefore, result is an estimated concentration (CLP J-Flag). The J flag is equivalent to the DNQ Estimated Concentration flag.