



basic
laboratory

www.basiclab.com

voice 530.243.7234

fax 530.243.7494

2218 Railroad Avenue

Redding, California 96001

Report To:

Attention:

Project: GENERAL TESTING EAST SHASTA LAKE

Description: BELLA VISTA LAKE SHASTA

Matrix: Water

(Rain)

Lab ID: 8100339-01

Lab No: 8100339

Reported: 10/22/08

Phone: [REDACTED]

P.O. #

Sampled: 10/04/08 08:00

Received: 10/08/08 15:08

Metals - Total

Analyte	Units	Results	Qualifier	MDL	RL	Method	Analyzed	Prepared	Batch
Aluminum	ug/l	84	J	30	100	EPA 6010B	10/14/08	10/09/08	B8J0258

Notes and Definitions

J Detected but below the Reporting Limit; therefore, result is an estimated concentration (CLP J-Flag). The J flag is equivalent to the DNQ Estimated Concentration flag.
DET Analyte DETECTED
ND